

SERVICE BULLETIN

<input type="checkbox"/>	Action Required
<input checked="" type="checkbox"/>	Only If Encountered
<input type="checkbox"/>	Information Only

To: All Dealers and Customers
Bulletin Number: B170007A-14
Date: 26-May-2017
Brands: Poulan Pro
Product: Gas blowers
Dates Produced: Prior to May 3, 2017
Affected Market(s): North America

Description/Background:

The starter pulley can become misshaped when experiencing elevated temperatures during starting of the unit.

Action Required:

- Units not yet sold to consumers are not approved for this service; service is required only if the issue is encountered on a customer's unit.
- Service includes replacing the pulley.
- Normal warranty applies.

Warranty Reporting:

Must perform service through Husqvarna's warranty process using only this information:

- Component code: **227 – Starter pulley**
- Defect code: **92 – Part exchanged on request by Husqvarna**
- Warranty type: **1 – warranty**
- Time Units: **4 units (24 minutes)**

Part Ordering:

Old part number: 545150201
Description: Starter pulley

New part number: **589505501**
Description: **Pulley service kit**

Affected Serial Number Range:

All produced prior to May 3, 2017; the serial numbers include all prior to **17123NXXXXX**.

Serial number format information:

17 = Year produced

123 = Consecutive day of the year (123/365)

Models Affected:

BVM200, PPB25

If you have questions, contact us.

Husqvarna Dealers call 1-800-448-7543

All other customers call 1-800-487-5951