



<input type="checkbox"/>	Action Required:
<input type="checkbox"/>	Sold
<input type="checkbox"/>	Not Sold
<input type="checkbox"/>	Only If Encountered
<input checked="" type="checkbox"/>	Information Only

SMB, LCT Engine – CE-Shield improvement, Poulan Pro Snow Throwers, PR240, PR241, PR270, PR270A, PR271, PR271A, PR300, 2018-01

Affected Models

Model	PNC	Serial Range Start	Serial Range End
PR240	961920067	050116MXXXXXX	093016MXXXXXX
PR241	961920092	050116MXXXXXX	093016MXXXXXX
PR270	961920090	050116MXXXXXX	093016MXXXXXX
PR270A	961920096	050116MXXXXXX	093016MXXXXXX
PR271	961920091	050116MXXXXXX	093016MXXXXXX
PR271A	961920097	050116MXXXXXX	093016MXXXXXX
PR300	961920071	050116MXXXXXX	093016MXXXXXX

Affected Market(s)

United States and Canada

Description

During internal testing it was discovered that CE-Shields on LCT engines had the potential to develop cracks. The engine supplier corrected this issue by increasing the material thickness from 0.9mm to 2mm.

	Product sold to end users	Residual inventory not yet sold
What is required	Service is not approved	Service is not approved
When to do	N/A	N/A
What to do	Information only	
How to do	Information only	

Parts Information

New part number	Part description	Quantity	Old part number
532436672	CE-Shield	1	N/A

Warranty Reporting Information

N/A – Warranty is not approved; information only.

Revision History

Revision	Date	Description
A	01-2018	Created

Confidential

Not for distribution to dealers or others outside Husqvarna Group.